SUMIDAS AUTO REPAIR

866 Kawaiahao St HONOLULU, HI 96813 Tel: 808-533-2994 • Fax: 808-533-1572 sumidasautorepair@gmail.com • www.sumidasautorepair.com Repair Order J016658

Service Advisor: JUAN VALDEZ Technician: JOHN-LESTER PASCUAL Date: 10-25-2023 08:26 AM

Estimate: Q009876

Kern Dept. Of Attorney General (DEP005)

425 Queen St Honolulu HI 96813 *Cell: 808-478-2112

KERN.K.NISHIOKA@HAWAII.GOV

2006 Porsche Cayenne Turbo

License Plate: 380TTT HI

Miles In:

89,828

4.5 GAS

WP1AC29P26LA90880

Miles Out: 89,828

CUSTOMER ISSUES AND ADVISORIES

Symptoms and Diagnostic Trouble Codes

IDLE ISSUES/ RUNS ROUGH

SITTING FOR A WHILE / ONCE BATTERY REPLACED, STARTED HAVING IDLE ISSUES

HAS FRESH GAS

Work Description

DIAG HARD TO START. NO ACCELERATION. CHECK FUEL PRESSURE AND FOUND SYSTEM AT 15PSI. SPEC IS 58PSI. COLLECTED FUEL SAMPLE AND FOUND FUEL TARNISHED/BROWN AND GUMMY. RECOMMEND FUEL PUMP/ FILTER AND SEALS. CLEAN OUT FUEL TANK AND CONTINUE DIAG. CHECK ENGINE LIGHT MAY STILL BE ON DUE TO BAD FUEL THAT WAS INSIDE. MAY HAVE CONTAMINATED SPARK PLUGS/ INJECTORS. ADVISED CUSTOMER OF ISSUES AND ONLY APPROVED FUEL PUMP/ FILTER. REPLACE FUEL PUMPS/ FILTER/ SEALS. CLEAN OUT FUEL TANK. REASSEMBLE AND START VEHICLE. VEHICLE NOW STARTS AND RUNS. ABLE TO ACCELERATE. FEELS LIKE SLIGHT ROUGH IDLE. RECOMMEND TO REPLACE FUEL INJECTORS AND SPARK PLUGS. ADD FUEL AND NOTICED FUEL LEVEL GAUGE DOES NOT MOVE. CHECK AND FOUND POSSIBLE ISSUE WITH CLUSTER.

WORK TO BE PERFORMED					
Labor					
Labor	Tech	Hrs	Price	Total	
DIAG		1.00	160.00	160.00	
SubTotal: Labor			17	\$160.00	
Fuel Pump					
Labor	Tech	Hrs	Price	Total	
Replace - Fuel Pump - Both		3.10	160.00	496.00	
Parts	Part No	Qty	Price	Total	
Fuel Pump Tank Seal	AAA955 201 133 01WP	2.00	13.99	27.98	
Fuel Tank Sending Unit	AAA955 620 805 00WP	1.00	196.08	196.08	
Fuel Tank Sending Unit	AAA955 620 806 01WP	1.00	196.08	196.08	
Fuel Pump Assembly	AAA955 620 931 01WP	1.00	402.89	402.89	
Fuel Pump Assembly	AAA955 620 932 01WP	1.00	402.89	402.89	
Fuel Filter	AAA955 620 841 00WP	1.00	130.43	130.43	
SubTotal: Fuel-Pump.				\$1,852,35	
Labor					
Labor	Tech	Hrs	Price	Total	
DRAIN/CLEAN FUEL TANK		1.50	160.00	240.00	
SubTotal: Labor		100	127	\$240.00	
Parts					
Parts	Part No	Qty	Price	Total	
FUEL	AAAFSGS	1.00	40.00	40.00	
SubTotal: Parts				\$40.00	

SUMIDAS AUTO REPAIR

Repair Order J016658
Date: 10-25-2023 08:26 AM

Kern Dept. Of Attorney General (DEP005) • 2006 Porsche Cayenne Turbo

Tel: 808-533-2994 • Fax: 808-533-1572

Labor	896.00
Parts	1,396.35
Hazmat*	0.00
Supplies*	25.00
Taxes	109.19

Repair Order Total \$2,426.54

^{*} Shop Supply & Hazmat Fees: This charge represents costs to this repair facility for miscellaneous shop supplies, and/or waste removal

0.00	Method	Authorizer	Date/Time:
		rure ·	XCustomer Signat
		ure	XCustomer Signat

ALL PARTS AND LABOR 12 MONTH /12000 MILE WARRANTY UNLESS OTHERWISE NOTED. PARTS THAT ARE WARRANTIED MAY BE SUBSTITUTED IF SUPPLY IS NOT AVAIABLE OR A REFUND MAY BE GIVEN FOR PARTS ONLY.ALL QUOTES AND ESTIMATES VALID FOR 30 DAYS

Payment Approved:

Goods/Sys, Satisfactorily Received

Date Goods/Svs. Rec'd:

10/2 Date Invoice Rec'd:

> 11:19:58 XXXXXXXXXX3356 808-533-2994 SUMIDAS AUTO REPAIR 866 KAWAIAHAO STREET HONOLULU, HI 96813 CREDIT CARD MC SALE ax Amount: